

**DLM CN2-210-2**

**MP 3.9 2/18/2010**



**PACK RUST AT GIRDER/CAP CONNECTION**



**SECTION LOSS TO TOP FLANGE OF BENT CAP**



**PACK RUST OF COVER PLATE SOUTH BENT CAP**



**RUST ON NORTH BENT CAP**

**DLM CN2-210-2 MP 3.9 2/18/2010**



**PITTING OF CENTER SPAN GIRDER**



**GIRDER PITTING MEASURE 1/16" DEEP**



**GIRDER AND DIAPHRAGMS PITTING  
IN CENTER SPAN**



**RUST ON NORTH BENT CAP**



**RUST PITTING ON BOTTOM FLANGE OF CENTER SPAN GIRDERS**



**RUST ON GIRDER ENDS UNDER DECK JOINTS**



**RUST ON BENT CAP**



**RUST PITTING 1/16" DEEP**



**RUST PITTING OF DIAPHRAGM**



**RUST PITTING OF BOTTOM FLANGE**



**RUST PITTING OF BOTTOM FLANGE**



**RUST PITTING OF TOP FLANGE AND WEB**

**DLM CN2-210-2 MP 3.9 2/18/2010**



**PACK RUST AT BENT/GIRDER CONNECTION**



**RUST W/SECTION LOSS TO GIRDER  
ENDS UNDER DECK JOINT**



**SECTION LOSS TO TOP OF BOTTOM  
FLANGE OF CENTER SPAN GIRDER**



**COLLISION DAMAGED RAIL POST**



**RUST W/SECTION LOSS AT TOP  
OF STEEL COLUMN**



UP MILEPOST



ELEVATION



LOOKING EAST



LOOKING WEST